

COOP MINING COMPANY

P.O. Box 1245
Huntington, Utah 84528



Office (435) 687-2450
FAX (435) 687-2084

Coal Program
Utah Division of Oil, Gas & Mining
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

April 10, 2001

Wild Horse
[Signature]
[Signature]
Copy letter to
Daron

To Whom It May Concern,

Re: Wild Horse Ridge Bond Calculation deficiencies, Bear Canyon Mine, ACT/015/025-98-1, Emery County, Utah

Enclosed are 6 copies of pages 3-83 thru 3-86, 3-94 thru 3-95, 3-1013-103 thru 3-107 and 3-110. A seventh copy has been delivered to the Price Field Office. These pages reflect revisions to the bond calculations which were necessary per verbal conversation with Wayne Western. The pages have been submitted in redline/strikeout format to illustrate the proposed changes. Following is a summary of the revisions:

1. The equipment production and efficiency information has been reviewed and updated from the CAT performance handbook. The 235D excavator has been upgraded to a 330BL excavator.
2. The "Wild Horse Ridge Surge Bin" name has been changed to "Wild Horse Ridge Coal Storage Bin" to correlate with Appendix 3-A.
3. Bond calculations have been added for the power lines & poles (pg. 3-101).
4. Wild Horse Ridge Blind Seam Portal Pad reclamation has been revised to distinguish between regrading work to be completed with a D9 Dozer and an Excavator.
5. The bond calculations for hauling the topsoil to the Wild Horse Ridge has been added (pg. 3-106).
6. The # of acres receiving hydroseeding in the "revegetation" section has been corrected.

Please replace the previously submitted pages listed above with the enclosed pages. If you need any additional information for the determination of the bond amount, please let me know.

Thank You,

Charles Reynolds

Charles Reynolds
Environmental Coordinator

RECEIVED

Enclosure(s)

DIVISION OF
OIL, GAS AND MINING